

## NOTES:

Α

1.) VACUUM SEAL SURFACE

2. FINISH: BEAD BLAST INSIDE & OUT 3. PROTECT ALL SURFACES FROM SCRATCHES, GOUGES & TOOLING MARKS DURING HANDLING. 4. GATE O-RING ON GATE

